


## Subminiature PCB Telecom Relay with Bifurcated Contacts

## PC332 - Obsolete



Values can change due to the switching frequency, desired reliability levels, environmental conditions, and in-rush current levels. It is recommended to test to actual load conditions for the application. It is the users responsibility to determine the performance suitability for their specific application. The use of any coil voltage less than the rated coil voltage may compromise the operation of the relay.



14680 James Road, Rogers, MN 55374 USA Sales (763) 535-2339 www.PickerComponents.com email: sales@PickerComponents.com