

January, 2010


Discontinuation of ALZ2 Relay



- 1. Reason: Replaced by newly released ALZ5 relay
- 2. Affected parts:

Target product	Types	Target part number	Direct replacement
LZ (ALZ) relays	PC board terminal 1 Form A type	ALZ22000	ALZ5OOOO

- 3. Last time buy: End of November 2010
- 4. Substitution: ALZ5 relay (drop-in replacement)
- 5. Product update: Removal of dummy contact (Cu); movable contact change from AgSnO₂ (solid) to AgSnO₂ (Ag+Cu bonded); housing marking change.



Panasonic Electric Works Corporation of America

- Head Office: 629 Central avenue, New Providence, NJ 07974
- Telephone: (908) 464-3550
- Fax: (908) 464-5719